



1. To deburr, the sharp angle is too blunt;
2. Heating the temperature to 300°C, the parts do not deform;
3. Reference to 3D drawing without annotated dimension;
4. The surface to prevent scraping, bumping, crushing, deformation and other bad.
5. Surface treatment: hard chromium plating;

[illegible]