

There is about 500mS delay when resuming charging from suspend state.

below register setting can avoid such 500mS delay:

clear 0x1052[1] CHG_ENB_TIEMOUT_SETTING

and

clear 0x1053[6] CHG_ADDITIONAL_300MS_HOLDOFF_TIMER_EN

Qualcomm
2019-04-09 04:03:48 PDT
zk_sw@wingtech.com