



MOTOR POWER INPUT (+12V)

The diagram shows a power supply section with a GND terminal and a +12V terminal (represented by a battery symbol and labeled +VDC). These are connected to a 4-pin screw terminal block labeled "Screw_Terminal_01x04 J3". The connections are as follows:

- Green wire: GND to terminal 4
- Red wire: +12V to terminal 3
- Blue wire: +12V to terminal 2
- Yellow wire: +12V to terminal 1

Terminals 1 and 2 are crossed with an 'X', and terminals 3 and 4 are crossed with an 'X'.

SAMPLE WHEEL MOTOR

MASK WHEEL MOTOR

Rev: 1.0.0
Id: 1/1