

AQUA DOC

Lake & Pond Management and Supplies

6475 Perimeter Dr., Suite 200

Dublin, Ohio 43016

www.aquadocinc.com

(614) 506-4166

1-800-689-5253

October 13, 2011

Mr. John Seymore
Powell Place HOA
717 Village Park Dr.
Powell, OH 43065

Dear John,

Enclosed are the results of the pond study. As you can see, there is some build-up on the east end, but otherwise there seems to be good depth overall.

Please let me know if you have any questions.


Sincerely,

Wayne R. Rolsen
Regional Manager
AQUA DOC Columbus

AQUA DOC...Working full time on Lake Management...So you don't have to.

1 N

MEASUREMENTS IN FEET
CIRCLED NUMBERS INDICATE SEDIMENT DEPTH



10/13/2011

POND DEPTHS (FT.)

| | | A | B | C | D | E | F | G | H | I | J |
|----|----------|-----|-----|-----|---|---|---|---|---|---|---|
| 1 | WATER | 2.5 | 6.0 | 5.5 | | | | | | | |
| | SEDIMENT | 1.0 | 2.0 | 1.5 | | | | | | | |
| 2 | WATER | 5.0 | 7.5 | 7.0 | | | | | | | |
| | SEDIMENT | 1.0 | 1.5 | 2.0 | | | | | | | |
| 3 | WATER | 5.0 | 7.5 | 7.0 | | | | | | | |
| | SEDIMENT | 1.0 | 2.0 | 2.0 | | | | | | | |
| 4 | WATER | 5.5 | 7.5 | 7.0 | | | | | | | |
| | SEDIMENT | 1.0 | 2.0 | 2.0 | | | | | | | |
| 5 | WATER | 6.5 | 6.0 | 3.0 | | | | | | | |
| | SEDIMENT | 1.0 | 1.5 | 1.0 | | | | | | | |
| 6 | WATER | | | | | | | | | | |
| | SEDIMENT | | | | | | | | | | |
| 7 | WATER | | | | | | | | | | |
| | SEDIMENT | | | | | | | | | | |
| 8 | WATER | | | | | | | | | | |
| | SEDIMENT | | | | | | | | | | |
| 9 | WATER | | | | | | | | | | |
| | SEDIMENT | | | | | | | | | | |
| 10 | WATER | | | | | | | | | | |
| | SEDIMENT | | | | | | | | | | |

10/13/2011