











magnets 56mm radius

TODO

Testpoints!
 mcu check if crystal is needed
 mcu check ref design
 mcu does reset need pullup?
 MCU reassign pins
 mcu pwm signal connected to random pin
 prog connector footprint: long pads are only needed on bottom layer, others can be normal, to make routing easier





