



Figure 10 shows a large, flat, and relatively smooth area of the fracture surface, which is characteristic of a ductile fracture process. This area is surrounded by a rougher, more irregular surface, indicating a transition to a different fracture mechanism.

Invoice No.	Dated
2846	2-Feb-23
Delivery Note	
Reference No. & Date.	Other References
Buyer's Order No.	Dated
Dispatch Doc No.	Delivery Note Date
Dispatched through	Destination
ROAD	AVINASHI
Bill of Lading/LR-RR No.	Motor Vehicle No.
	TN39DX8466

701400 1,582.7

Only

VINAYAKA ROOFING PRODUCTS
PERUNDURAI