



TROUBLE SHOOTING REPORT

PSMD (SABHAN)

Ref. No:	93/05/21	Date:	10/05/2021	Prnt.Time :	10:21
Substation:	MERGAB-A	Make:	ABB	P.M:	01/03/2017
		Maint:	ABB	Comm:	06/08/1977

Equip./Unit Affected : Hilalli "M" 33kV F# 3

Nature of Fault : COPA circuit low insulation from Control panel to Oil Guage. Reported by CME Mohd. Desuge (Mobile # 60012428). PME has to follow.

Mohammad Ahmad

Concerned Group & Engr: Mohammad **Technicians:-** 1-

Section Head : 2-

Action Taken :

Visit S/S for mentioned alarm. No alarm found. Checked COPA wire is in good condition.

Contacted CME Mohd.Desuge. He informed me that COPA wire is replaced due to joints in old wire. And s/s clear.

informed DCC.

Concerned Group & Engr :

Date: / /

Director :

Section Head :