




## 22. IR-sensor assembly



- Finish the sensor assembly by inserting an M3x40 screw.
- Make sure all the gaps are gone.

[Next →](#)