








## 2. Z-axis: assembling motor holders




**WARNING: Printed parts aren't the same!** There is a left and right oriented piece. See the markings on the parts. Also note the correct orientation of the frame, the **"PRUSA" logo** and **the safety sticker must be facing towards you.**

**For the following step, please prepare:**

-  Z-axis-bottom-left (1x)
-  Z-axis-bottom-right (1x)
-  M3x10 screw (6x)

**Place the printed parts next to the frame. See the left (L) and right (R) marking on the printed parts.**

-  Tighten each printed part with M3x10 screws. **Don't use excessive strength during tightening!** In case of increased resistance, try to place the screws from the other side to "clean up" the hole. Then return to the front side.



Next →

