





50. Extruder channels cable management



-  Place the cables on the SuperPINDA sensor side over the lower smooth rod and push them back in the channel.
-  Place the cables on the hotend fan side over the lower smooth rod and push them back in the channel.
-  Align the bearing, so it fits nicely in the X-carriage.



Next →

