


13. Hotend assembly



- Take two M3x10 screws and insert them in the holes. Doing this now makes the assembly slightly easier, but both holes are shallow and the screws might fall out. If this happens, you can continue without them and put them back later on (you will be notified later). *Also note, that in few upcoming pictures the screws might be missing.*
- Place the hotend next to the Extruder-body, see the grooves in the printed part, which are in the shape of the hotend.
- Correctly placed hotend. The hotend cables should point to the left, we will align them in the next step.



Next →

