



66. X-carriage-back assembly



For this step, please prepare:



M3x10 screw (4x)



Before you tighten the X-carriage-back, arrange all cables, make sure none is pinched.



Use all four screws and tighten the X-carriage-back.



Tighten the screws with a reasonable force, make sure you won't deform/squeeze the bearings between the printed parts.



Next →

