









## 5. X-axis: trapezoidal nuts (part 1)



### For the following step, please prepare:

-  Trapezoidal nut (2x)
  -  M3x18 screw (4x)
  -  M3n nut (4x)
  -  Turn the X-axis upside down and insert nuts into traps on both X-ends.
-  In case you can't press the nuts in, don't use excessive force. First, check that there isn't any obstacle in the nut trap.



Next →

