


## 35. Y-axis: Assembling the belt



- Using M3x10 screw fix the Y-belt-tensioner to the Y-carriage. **Don't tighten the screw completely**, we need to adjust the position of the printed part.
- Use the hole on the right, see the picture.
- Insert the M3x30 screw through both printed parts. Start tightening until you reach the M3nN nyloc nut.



Next →

