




8. Placing the Z-axis-top parts (part 1)



For the following steps, please prepare:



Z-axis-top-left (1x)



Z-axis-top-right (1x)



M3x10 screw (4x)



Next →

