









12. Hotend parts preparation



For the following steps, please prepare:

-  Hotend for the MK3S+ (1x)
-  M3x40 screw (2x)
-  M3x10 screw (2x)
-  We will use one M3x40 later on, keep it around.
-  Don't cut the main zip tie on the hotend cables, or remove the rubber band, it will make the assembly easier.



Next →

