







## 39. Pretensioning the Extruder-idler



-  Use the M3x40 screw with the spring to introduce tension to the Extruder-idler.
-  Hold the Extruder-idler on the other side, until the screw reaches the nut.
-  Since there is only one screw, you need to introduce a large force. The head of the screw should be roughly aligned/flush with the surface. This can be adjusted later.



Next →

