







## 8. Y-axis: preparation for the PSU



 **THIS IS A VERY IMPORTANT STEP!** Incorrect placement of PSU holders will lead to issues later.

-  Take the YZ frame and rotate it with the shorter extrusions towards you.
-  Place the PSU holders (M3nE/M3nEs) in the extrusion, **use the side section**, ensure it is the correct extrusion. See the picture.
-  Both the holders goes only into one of the extrusions. The exact spacing of the PSU holders doesn't matter, we will adjust them later.



Next →

