


36. Extruder-idler mounting



- Place the Extruder-idler in place.
- Secure it using the M3x40 screw.
- Don't tighten the screw too firmly, it serves as a shaft for the idler. Check that the idler can rotate freely.



Next →

