







36. Extruder-idler mounting



-  Place the Extruder-idler in place.
-  Secure it using the M3x40 screw.
-  Don't tighten the screw too firmly, it serves as a shaft for the idler. Check that the idler can rotate freely.

[Next →](#)