

PCB ID: pcb_2

Missing_hole - Severity: 9 - Cause: Drilling issue

Spurious_copper - Severity: 5 - Cause: Etching problem

Spur - Severity: 4 - Cause: Etching / unwanted copper

Spur - Severity: 4 - Cause: Etching / unwanted copper