

PCB ID: image_2025-09-27_222056179

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Spurious_copper - Severity: 5 - Cause: Etching problem

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Short - Severity: 9 - Cause: Soldering/printing issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Missing_hole - Severity: 9 - Cause: Drilling issue

Spurious_copper - Severity: 5 - Cause: Etching problem

Missing_hole - Severity: 9 - Cause: Drilling issue