

Super-Secret Test 0.1

Location: Coeur d'Alene Beach Dock

Travel Report:

No issues loading up the submarine and handling gear. Secret testing location is within walking distance. Seemed harder this time but possibly due to hotter weather.

Test Report:

Testing started out well, but some issues arose during progression of the testing process. Testing process report is as follows:

- General assembly and extension of the handling gear progressed well. There were no issues with the step-by-step process up to attaching the tether to the submarine.
- Upon disengaging the tether to untangle the wires, it is highly probable that the pins touched metal. This could've happened either upon removing the plug or reattaching the plug.
- Due to the pins touching metal, the power fuse inside the submarine blew. This rendered us unable to communicate with the submarine. Upon exhaustion of all possible on-site tests, we returned to the lab.
- Marty was called in to assist with testing the tether and other possible causes of loss of submarine communication abilities. With his help, the cause listed above was found.
- After procurement of new fuses, we will be able to proceed with the next test.

Extra Notes: A laptop cover to protect from the sun would be nice to avoid heating the laptop. Sunscreen is advisable as we burned. Water would also be good.