

# NDT INSPECTION REPORT SAMPLE

Report ID: NDT-54-2029-0234

Component: Fan Cowl Panel

Method: Ultrasonic C-Scan

Result: Delamination detected 75mm x 45mm

This is a sample NDT report.

In production would include C-scan images and data.