

创建统计过程控制图表

©Maplesoft, a division of Waterloo Maple Inc., 2008

描述

创建SPC（统计过程控制）图表。


使用工具-分析助手中的输入数据任务助手输入数据文件，或者在命令行中以数组的形式输入数据。

```
> Array([21, 24, 16, 12, 15, 5, 28, 20, 31, 25, 20, 24, 16, 19, 10, 17, 13, 22, 18, 39,
        30, 24, 16, 19, 17, 15])
```

1 .. 26 Array
Data Type: anything
Storage: rectangular
Order: Fortran_order


绘制 C 图表。

```
> ProcessControl[CChart](1, 100, title
    = "Nonconformities for Printed Circuit Boards - n = 100", labels =
    ["Sample Number", "Nonconformities"], labeldirections
    = [horizontal, vertical])
```




绘制 U 图表。

```
> ProcessControl[CChart](1, 100, title
    = "Nonconformities for Printed Circuit Boards - n = 100", labels =
    ["Sample Number", "Nonconformities"], labeldirections
    = [horizontal, vertical])
```




绘制 P 图表。

```
> ProcessControl[PChart](1, 50, title
    = "Nonconforming Cans - n = 50", labels = ["Sample Number",
    "Sample Fraction Nonconforming, p"], labeldirections
    = [horizontal, vertical])
```



绘制 NP 图表。

```
> ProcessControl[NPChart]((1), 50, title
= "Nonconforming Cans - n = 50", labels = ["Sample Number",
"Sample Nonconforming, np"], labeldirections = [horizontal,
vertical])
```



所用命令

[Array](#), [ProcessControl\[CChart\]](#), [ProcessControl\[NPChart\]](#), [ProcessControl\[PChart\]](#),
[ProcessControl\[UChart\]](#)

参见

[ProcessControl](#), [ProcessControl\[CControlLimits\]](#), [ProcessControl\[NPControlLimits\]](#),
[ProcessControl\[PControlLimits\]](#), [ProcessControl\[UControlLimits\]](#), [Statistics](#)

本文件位置：文件 -> 新建... -> 模版.. -> CreatSPCCharts.mw

更多资料：www.cca-es.com