

Firmware Release Notes

Copyright © 2023 New H3C Technologies Co., Ltd. All rights reserved.

No part of this manual may be reproduced or transmitted in any form or by any means without prior written consent of New H3C Technologies Co., Ltd.

Except for the trademarks of New H3C Technologies Co., Ltd., any trademarks that may be mentioned in this document are the property of their respective owners.

This document provides generic technical information, some of which might not be applicable to your products.

The information in this document is subject to change without notice.

Contents

Description	1
New functions	1
List of resolved problems	1
Fixed security vulnerabilities	1
Restrictions and guidelines	1
Upgrade procedure	1
Version information	1
Upgrade recommendations	1

Description

The software is the update program of firmware GXG3 of the Samsung PM1653 series drives.

New functions

None.

List of resolved problems

1. Device detection failure after hard reset operation - If the other port gets 1st CMD while one port is under hard rest operation, device ignores the 1st CMD.
2. Lack of DRAM error logging.
3. Read failure during temperature swing power cycle.
4. Task management function(TMF) failure during WriteSame(unmap) process.

Fixed security vulnerabilities

None.

Restrictions and guidelines

Before updating software versions, make sure you understand the software feature changes between versions, evaluate the potential impact of changes on your business, and refer to the relevant supporting documentation.

Upgrade procedure

See the drive firmware update user guide.

Version information

N/A

Upgrade recommendations

Upgrade the firmware as a best practice.