


61 Boundary Drive, Stafford, VA 22556

Report: 60713723



In this 3D model, facets appear as semi-transparent to reveal overhangs.

Building: PS

Claim Information

PO Number: 433

PREPARED FOR

Contact: Judd Addy
Company: Insured Roofs LLC
Address: 212 Choptank Rd
Stafford, VA 22556-6439
Phone: 571-699-6332

TABLE OF CONTENTS

Images	1
Length Diagram	4
Pitch Diagram	5
Area Diagram	6
Notes Diagram	7
Report Summary	8

MEASUREMENTS

Total Roof Area =1,599 sq ft
Total Roof Facets =4
Predominant Pitch =6/12
Number of Stories >1
Total Ridges/Hips =48 ft
Total Valleys =0 ft
Total Rakes =100 ft
Total Eaves =96 ft

Measurements provided by www.eagleview.com



Certified Accurate

www.eagleview.com/Guarantee.aspx

61 Boundary Drive, Stafford, VA 22556

Report: 60713723

IMAGES

The following aerial images show different angles of this structure for your reference.

Top View



IMAGES

North Side



South Side



61 Boundary Drive, Stafford, VA 22556

Report: 60713723

IMAGES

East Side



West Side



61 Boundary Drive, Stafford, VA 22556

Report: 60713723

LENGTH DIAGRAM

Total Line Lengths:

Ridges = 48 ft
Hips = 0 ft



Valleys = 0 ft

Rakes = 100 ft

Eaves = 96 ft

Flashing = 0 ft

Step flashing = 30 ft

Parapets = 0 ft


©2024 Eagle View Technologies, Inc., All Rights Reserved.


Note: This diagram contains segment lengths (rounded to the nearest whole number) over 5.0 Feet. In some cases, segment labels have been removed for readability. Plus signs preface some numbers to avoid confusion when rotated (e.g. +6 and +9).

61 Boundary Drive, Stafford, VA 22556


Report: 60713723

PITCH DIAGRAM

Pitch values are shown in inches per foot, and arrows indicate slope direction. The predominant pitch on this roof is 6/12



©2024 Eagle View Technologies, Inc., All Rights Reserved.




Note: This diagram contains labeled pitches for facet areas larger than 20.0 square feet. In some cases, pitch labels have been removed for readability. Blue shading indicates a pitch of 3/12 and greater.

61 Boundary Drive, Stafford, VA 22556


Report: 60713723

AREA DIAGRAM

Total Area = 1,599 sq ft, with 4 facets.




© 2024 Eagle View Technologies, Inc., All Rights Reserved.




Note: This diagram shows the square feet of each roof facet (rounded to the nearest Foot). The total area in square feet, at the top of this page, is based on the non-rounded values of each roof facet (rounded to the nearest square foot after being totaled).

NOTES DIAGRAM

Roof facets are labeled from smallest to largest (A to Z) for easy reference.



© 2024 Eagle View Technologies, Inc., All Rights Reserved.



Note: This diagram also appears in the Property Owner Report.

61 Boundary Drive, Stafford, VA 22556

Report: 60713723

REPORT SUMMARY

All Structures

Areas per Pitch

Roof Pitches	6/12
Area (sq ft)	1599.0
% of Roof	100%

The table above lists each pitch on this roof and the total area and percent (both rounded) of the roof with that pitch.

Structure Complexity

Simple	Normal	Complex
--------	--------	---------

Waste Calculation


NOTE: This waste calculation table is for asphalt shingle roofing applications. All values in table below only include roof areas of 3/12 pitch or greater. For total measurements of all pitches, please refer to the **Lengths, Areas, and Pitches** section below.

Waste %	0%	4%	7%	9%	11%	14%	19%	24%	29%
Area (Sq ft)	1599	1663	1711	1743	1775	1823	1903	1983	2063
Squares *	16.00	16.66	17.33	17.66	18.00	18.33	19.33	20.00	20.66
	Measured			Suggested					

* Squares are rounded up to the 1/3 of a square

Additional materials needed for ridge, hip, and starter lengths are not included in the above table. The provided suggested waste factor is intended to serve as a guide—actual waste percentages may differ based upon several variables that EagleView does not control. These waste factor variables include, but are not limited to, individual installation techniques, crew experiences, asphalt shingle material subtleties, and potential salvage from the site. Individual results may vary from the suggested waste factor that EagleView has provided. The suggested waste is not to replace or substitute for experience or judgment as to any given replacement or repair work.

All Structures Totals



Total Roof Facets = 4

Lengths, Areas and Pitches

Ridges = 48 ft (2 Ridges)
Hips = 0 ft (0 Hips).
Valleys = 0 ft (0 Valleys)
Rakes[†] = 100 ft (6 Rakes)
Eaves/Starter[‡] = 96 ft (4 Eaves)
Drip Edge (Eaves + Rakes) = 196 ft (10 Lengths)
Parapet Walls = 0 (0 Lengths).
Flashing = 0 ft (0 Lengths)
Step flashing = 30 ft (2 Lengths)
Predominant Pitch = 6/12
Total Area (All Pitches) = 1,599 sq ft

Property Location

Longitude = -77.5545697
Latitude = 38.5042315

Notes

This was ordered as a residential property. There were no changes to the structure in the past four years.

[†] Rakes are defined as roof edges that are sloped (not level).

[‡] Eaves are defined as roof edges that are not sloped and level.

61 Boundary Drive, Stafford, VA 22556

Report: 60713723

Online Maps

Online map of property

http://maps.google.com/maps?f=g&source=s_q&hl=en&geocode=&q=61+Boundary+Drive,Stafford,VA,22556

Directions from Insured Roofs LLC to this property

http://maps.google.com/maps?f=d&source=s_d&saddr=212+Choptank+Rd,Stafford,VA,22556-6439&daddr=61+Boundary+Drive,Stafford,VA,22556

61 Boundary Drive, Stafford, VA 22556

Report: 60713723

IMPORTANT LEGAL NOTICE AND DISCLAIMER**Notice and Disclaimer**

No Warranty: The Copyrighted Materials are provided to you "as is," and you agree to use it at your own risk.

EagleView Technologies makes no guarantees, representations or warranties of any kind, express or implied, arising by law or otherwise, including but not limited to, content, quality, accuracy, completeness, effectiveness, reliability, fitness for a particular purpose, usefulness, use or results to be obtained from the Copyrighted Materials.

Contractors agree to always conduct a preliminary site survey to verify Roof Report ordered. In the event of an error in a Report, your sole remedy will be a refund of the fees paid by you to obtain this Report.