





**PurgesRamp Toidle in
maxRampRate**

Check Spindle stop
Check Reactor
Pressure
and move to Idle fault
(alarm) when not
stopped

Enable Deviation Alarms



PM Flow
Idle