



DC MOTOR CONTROL SYSTEMS FOR ROBOT APPLICATIONS

By: Rick Bickle


11/7/2003



Motor control questions

- Why do we need speed control?
- How is DC motor speed controlled?
- How is motor direction controlled?
- What circuits can be used?

Reasons for accurate speed control




- Motor speed should be independent of load.
- Differential drive platforms need to synchronize wheel speed to go in a straight line.

Speed control with PWM


- Pulse Width Modulation

$$\text{Duty Cycle} = \frac{\text{Time Signal in High State}}{\text{Period of Cycle}} \times 100$$



$$\frac{0.5s}{1s} \times 100 = 50$$

Duty Cycle = 50%




$$\frac{4ms}{5ms} \times 100 = 80$$

Duty Cycle = 80%


The diagram illustrates a motor speed control circuit. It begins with a power supply section on the left, featuring a capacitor C1 (CAP NP) connected to ground. The supply line branches into two paths: one leading to the input (pin 1) of a Schmitt trigger inverter U1A (74HC14A), and another passing through a diode D1 to a central node. This central node also branches to the inputs (pins 3, 5, and 9) of three other 74HC14A inverters (U1B, U1C, and U1D). A second diode D2 is connected to the output (pin 2) of U1A and to a potentiometer R2 (POT). The wiper of R2 is connected to the input (pin 5) of U1C. The outputs of U1B (pin 4), U1C (pin 6), and U1D (pin 8) are connected to a common node that drives the input (pin 1) of a DC motor (MG1). The motor's other terminal (pin 2) is connected to ground. Additionally, there are two more inverters, U1E and U1F (both 74HC14A), which are not connected to any other components in this circuit. U1E has its input (pin 11) connected to the supply and its output (pin 10) is an open square. U1F has its input (pin 13) connected to ground and its output (pin 12) is an open square.

H-Bridge motor driver circuit

CIRCUIT INPUTS			
A	B	C	Output
0	0	0	N Channel Brake
1	1	0	P Channel Brake
1	0	0	Forward
0	1	0	Reverse
X	X	1	Motor Off




Optical encoder circuit





Motor control diagram





Control systems

- What is a control system?
- What are some examples?
- What are the types of control systems?
- How are control systems represented?




Open loop control systems

- The output of the plant does not affect the input. (No feedback)
- Less common today than closed loop control systems.
- Examples include:
 - Stereo volume control
 - Electric drill speed control



Open loop control system



$$\text{OUTPUT} = \text{INPUT} \times \text{GAIN}$$




Closed loop control systems

- Use a measurement of output to control the input (Feedback)
- Examples include:
 - Air conditioning thermostat
 - Automobile cruise control




Closed loop control system



$$\text{OUTPUT} = (\text{INPUT} - \text{OUTPUT}) \times \text{GAIN}$$



Motor control diagram






PID Closed loop control system

- PID controls the gain portion of the closed loop control system.
- PID algorithms adjust the gain to the plant based on several characteristics of the feedback, not just the current value.


PID control system diagram



$$\text{OUTPUT} = (\text{INPUT} - \text{OUTPUT}) \times (\text{P GAIN} + \text{I GAIN} + \text{D GAIN})$$

Sample PID output chart

- Set point
- Rise time
- Overshoot
- Settling time
- Peak time
- Overdamped
- Underdamped





PID implementation

- What is the mathematics of PID?
- How is it programmed?
- What are some common problems?
- How is the PID behavior optimized?




PID variables

- Error term
- P – Proportional gain
- I – Integral gain
- D – Derivative gain


Error term

- The error term is derived by subtracting the feedback (motor speed) from the set point (set speed).
- This is the error in terms of a number of encoder counts per unit time.




Proportional term

- Simple proportional coefficient K_p is multiplied by the error term.
- Provides linear response to the error term.




Integral term

- Integral coefficient K_i is multiplied by the error term and added to the sum of all previous integral terms.
- Provides response to accumulated error.



Derivative term

- Derivative coefficient K_d is multiplied by the difference between the previous error and the current error.
- Responds to change in error from one PID cycle to the next.





PID calculation example

- $\text{Error_term} = \text{Set_Speed} - \text{Encoder_Count};$
- $\text{P_Term} = \text{P_Gain} * \text{Error_Term};$
- $\text{D_Term} = \text{D_Gain} * (\text{Error_Term} - \text{D_State});$
- $\text{D_State} = \text{Error_Term};$
- $\text{I_State} = \text{I_State} + \text{Error_Term};$
- $\text{I_Term} = \text{I_Gain} * \text{I_State};$
- $\text{PWM_Set} = \text{PWM_Set} + \text{P_Term} + \text{I_Term} + \text{D_Term};$



Factors to consider

- PID cycle time (0.1 sec)
 - Motor speed (30 rpm)
 - Encoder resolution (500 counts/rev)
 - PWM frequency (1kHz)
- Interrupt driven PID trigger
 - Eliminates code tuning
 - Maintains accurate PID timing



Pitfalls of PID

- Integral windup
- PWM term overflow
- PID variable overflow



Integral windup prevention

```
I_State_L += error_L;           // Accumulate error in I_State
if (I_Term_L > I_Max)           // Check for integral windup
{
    I_Term_L = I_Max;
}
else if (I_Term_L < I_Min)
{
    I_Term_L = I_Min;
}
```



PWM overflow prevention

```
// *** Set Left PWM ***
```

```
fL += P_Term_L + I_Term_L + D_Term_L;
```

```
if (fL > 0xFF)
```

```
{
```

```
    fL = 0xFF;
```

```
    CCAP1H = 0xFF;
```

```
}
```

```
else if (fL < 0x00)
```

```
{
```

```
    fL = 0x00;
```

```
    CCAP1H = 0x00;
```

```
}
```

```
else
```

```
{
```

```
    CCAP1H = (unsigned char)(fL);
```

```
}
```

```
// Set PWM Output
```

```
// Check for PWM Overflow
```

```
// Limit fL to prevent windup
```

```
// Set upper limit for PWM Byte
```

```
// Limit fL to prevent windup
```

```
// Set lower limit for PWM byte
```



PID Tuning

- How is the response of the PID system tested and measured?
- How is the response of the PID system optimized?
- How are the coefficients for P, I, and D determined?




PID tuning (BLACK MAGIC METHODS)

- Mathematical methods
 - Mathematical representation of the plant
 - Root locus methods
 - State space equations
 - Laplace transforms
 - S – domain calculations
 - Is there a simpler way?

PID system measurement

- The behavior of most systems is measured by the system's "Step response"
- How can we measure a step response for our PID controller?





PID Tuning (Brute force approach)

- Add code to monitor the output of the PID algorithm (i.e. encoder speed feedback, counts per PID)
- Store the feedback speed value into an array element for the first 20 PID executions. (2 seconds)
- Change the set speed from 0 to 60% of the motor's maximum speed. (30 counts per PID) This is equivalent to a step function.
- After 2 seconds, stop the motor and print the array data to the serial port.
- This allows the response of the platform to be determined numerically.



PID Brute Force Tuning code

- The tuning algorithm loops through a range of values for each coefficient P, I, and D. For example:

```
for (P=P_start; P<P_end; ++P)
{
    For (I=I_start; I<I_end; ++I)
    {
        For (D=D_start; D<D_end; ++D)
        {
            Set motor speed to 30 counts/PID
            Wait for the motor to go 1000 counts
            Set motor speed to 0
            Print the P, I, and D values and the 20 array elements
        }
    }
}
```




0,0.001,	0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0,0
0,0.001,	1,8,14,11,7,4,4,1,1,0,0,0,0,0,0,0,0,0
0,0.001,	2,6,15,12,10,9,8,6,7,6,7,6,8,7,7,6,7,7,8
0,0.001,	3,5,12,12,12,11,11,11,10,10,11,10,11,11,12,11,12,12,11,12,12
0,0.001,	4,6,15,15,14,15,13,13,13,13,14,14,14,14,15,15,14,14,14,14,15
0,0.001,	5,8,16,17,17,16,14,14,14,16,16,16,16,16,18,17,16,15,17,16,15
1,0.001,	0,8,15,12,11,11,14,16,19,27,28,31,32,32,33,33,15,33,33,33,33
1,0.001,	1,5,12,10,11,14,17,21,24,25,27,28,31,31,32,32,32,32,33,32,32
1,0.001,	2,6,13,13,15,15,18,23,24,25,26,28,29,30,31,30,30,31,31,31,31
1,0.001,	3,7,14,16,17,19,20,23,23,25,25,28,29,29,29,30,30,29,31,30,31
1,0.001,	4,6,16,19,18,20,21,23,24,25,26,27,27,28,28,28,29,29,30,29,30
1,0.001,	5,6,18,22,21,22,22,23,23,25,26,27,27,28,28,28,28,29,29,29,30
2,0.001,	0,6,12,12,16,21,27,30,32,34,35,36,35,35,34,32,32,31,30,30,28
2,0.001,	1,6,13,15,19,23,26,29,31,32,34,33,34,0,32,32,32,31,31,30,30
2,0.001,	2,6,14,18,21,24,26,27,30,31,32,32,32,33,32,32,31,31,31,30,29
2,0.001,	3,5,18,21,23,26,27,28,30,29,29,29,28,28,30,29,30,31,31,31,32
2,0.001,	4,6,18,24,26,25,25,26,27,30,30,30,30,31,31,31,30,30,31,30,30
2,0.001,	5,6,19,27,26,26,26,26,28,29,30,30,30,30,29,31,30,30,30,30,31




PID Brute Force Tuning results

- Now the results of all PID values within the test range are plotted with respect to time.
- The values which yield the best curve will be used for the PID controller.


PID Tuning chart 1




PID Tuning chart 2




PID Tuning chart 3




PID Tuning chart 4




PID Tuning chart 5




PID Tuning chart 6



The optimum PID coefficients!



The completed control system





PID References

- Carnegie Mellon University
<http://www.engin.umich.edu/group/ctm/PID/PID.html>
- "PID Without a PHD" by Tim Wescott
<http://www.embedded.com/2000/0010/0010feat3.htm>



This concludes the presentation

Thank you for your attention