


One: The win10 system is the first time to install the V1.11.5~8 version SDK, the following prompts may appear:



Method: Copy the mfc140u.dll file to the installation directory and re-open the client as an administrator.

此电脑 > Windows (C:) > Program Files > AXonClient >				
名称	修改日期	类型	大小	
depthdata	2019/4/29 16:45	文件夹		
Image	2019/5/27 16:15	文件夹		
OpenNI2	2019/4/29 16:45	文件夹		
TestData	2019/4/29 16:45	文件夹		
AXON_Client	2019/1/24 15:21	应用程序	5,946 KB	
AXonClient	2019/4/29 16:45	Internet 快捷方式	1 KB	
DisCompensation	2018/8/9 14:17	配置设置	1 KB	
distanceE2	2018/8/9 14:17	配置设置	1 KB	
mfc140u.dll	2016/7/22 1:32	应用程序扩展	5,924 KB	
opencv_core320.dll	2018/8/6 19:21	应用程序扩展	10,649 KB	
opencv_imgproc320.dll	2018/8/6 19:21	应用程序扩展	22,041 KB	
opencv_world320.dll	2018/8/6 19:21	应用程序扩展	40,863 KB	
OpenNI	2018/8/9 14:17	配置设置	1 KB	
OpenNI2.dll	2019/1/24 14:25	应用程序扩展	289 KB	
OpenNI2.jni.dll	2019/1/24 14:25	应用程序扩展	62 KB	
pcl_common_release.dll	2018/8/9 14:17	应用程序扩展	570 KB	
pcl_in_nlv_release.dll	2018/8/9 14:17	应用程序扩展	310 KB	



Note: Subsequent versions will be fixed, temporarily resolved according to this method.



m fc140u.dll