



There are time delays between SM clock signal, GPIO output pin voltage, WS2812 serial input pin voltage, WS2812 LED supply voltage, WS2812 LED luminance and APDS-9960 photodiode output voltage. This is caused by hardware limitation.

