

COMPLETE SERVICE REPORT

Reference: SR-1764133049850298

BASIC INFORMATION

Priority: NORMAL
Status: COMPLETED
Created Date: 26/11/2025, 10:27:29 am

ISSUE DESCRIPTION

temperature required

Error Code: e45

Ø<ßâ Company Name: Crystal Group
Ø=ÜP Onsite Contact: 9876543210
Ø=ÜÍ Site Address: Goregaon West, Mumbai

& p Preferred Technician Call: Thu, 27 Nov

CLIENT DETAILS

Company: Hetero Labs Ltd - unit 3 (EOU)
Contact: Hetero Labs Ltd - unit 3 (EOU)
Phone: +000735978025
Address: Jeedimetla

CONTAINER DETAILS

Code: CXRU1326276
Type: refrigerated
Location: Oakland

ASSIGNED TECHNICIAN

No technician assigned

REQUIRED PARTS

1. SZ-N75-3000 sensor (Subzero) [5 mtr long] (2)
2. Asian Apcolite Black Paint 1 Ltr (1)
3. YAK Quick Drying Enamel Oxford Blue (2)
4. YARK Synthetic Black 1 Ltr (2)
5. Acetolene (1)

WORK PERFORMED

done

CONFIDENTIAL - This document contains proprietary information

