


Mount Z-Axis:
In addition, it will be necessary to mount the machine to a spoil board or bed.
Please see the wiki for details.

Shapeoko Build Instructions

STEP 13

http://www.shapeoko.com/wiki/index.php/Assembly_step_13



ITEM	QTY	PART NUMBER	TITLE
1	1	SM-GA01	Shapeoko Gantry Assembly
2	1	SM-FA01	Shapeoko - Frame Assembly
3	1	SM-ZA02	Z Axis Spindle Mount



OPEN HARDWARE
Attribution-ShareAlike 3.0
Unported
(CC BY-SA 3.0)

TOLERANCES
(EXCEPT AS NOTED)
BETWEEN
FINISHED SURFACES

FRACTIONAL: $\pm 1/64"$

DECIMAL: $\pm .010"$

DETAIL DIMENSIONS: $\pm 1/16"$

shapeoko

DESIGNED BY:
ERF

DETAILED BY:
ERF

DATE:
6/5/2012

TITLE

Shapeoko v1i

SIZE
B

DRAWING NUMBER
Shapeoko_v1i

SCALE

SHEET 1 OF 1