



# Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



0.719

Repair Quality Score

Good - Acceptable Repair

2026-01-27 15:26:12