



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



0.819

Repair Quality Score

Good Restoration - Acceptable Recovery

2026-01-29 20:38:37