



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



0.961

Repair Quality Score

Excellent - Nearly Perfect Repair

2026-01-17 20:07:46