



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



Overall Assessment

0.752
Repair Quality Score
Good - Acceptable Repair
2026-01-15 20:46:13