



# Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



Overall Assessment

**0.719**  
Repair Quality Score  
**Good - Acceptable Repair**  
2026-01-28 12:58:13