



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



0.857

Repair Quality Score

Very Good - Highly Effective Repair

2026-01-27 13:51:09