



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



Overall Assessment

0.469

Repair Quality Score

Poor - Minimal Improvement

2026-01-19 13:06:49