



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



Overall Assessment

**0.370**  
Repair Quality Score  
**Poor - Minimal Improvement**

2026-01-17 16:01:34