



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



Overall Assessment

0.570

Repair Quality Score

Fair - Partial Improvement

2026-01-19 13:15:32