



Structural Repair Quality Analysis Report


Natural Frequencies Comparison




Frequency Response Spectrum




Mode Shape Comparison (First 3 Modes)



Damping Ratios Comparison



Quality Score Breakdown



1.000

Repair Quality Score

Excellent - Nearly Perfect Repair

2026-01-11 22:22:23