






Structural Repair Quality Analysis Report



Overall Assessment

**0.466**

Repair Quality Score

**Poor - Minimal Improvement**

2026-01-17 20:55:24