



ND<N
L_OUTD<L_OUT
L_OUT2D<L_OUT2



If calibration is used, cut net ties and connect current transformer between TP1 and TP2. Otherwise, connect it between L_OUT and the load.



Sheet: /Calibration circuits for 230V/
File: calibrate.sch

Title:

Size: A4	Date:	Rev:
KiCad E.D.A. kicad 5.1.9-1.fc32		Id: 3/3