


**Cast Iron and Steel**

The term *steel* applies to any alloy consisting of iron and less than 1.5% carbon, and often other elements. When iron ore is treated with carbon in the form of coke to extract pure iron metal, some of the carbon also reacts with the iron to produce a form of iron carbide known as cementite. The reaction can be represented by the following equation.



Cast iron is a mixture that consists of some pure iron, known as ferrite, some cementite, and some carbon atoms trapped within the crystalline structure of the iron and cementite. The rate at which cast iron is cooled changes the proportion of these three components. If the cast iron is cooled slowly, the ferrite and cementite tend to separate from each other, forming

a banded product that is tough but not very hard. However, if the cast iron is cooled quickly, the components of the original mixture cannot separate from each other, forming a product that is both tough and hard.



*Stainless steel, which is hard and resists corrosion, is made of iron and chromium (12–30%). The properties of stainless steel make it a suitable alloy for making cutlery and utensils.*

**TABLE 3B** Composition and Uses of Some Alloys

Name of alloy	Composition	Uses
Brass	copper with up to 50% zinc, some lead, and a small amount of tin	inexpensive jewelry; hose nozzles and couplings; piping; stamping dies
Bronze	copper with up to 12% tin	coins and medals; heavy gears; tools; electrical hardware
Coin metal	copper: 75% nickel: 25%	United States coins
Duralumin	aluminum: 95% copper: 4% magnesium: 0.5% manganese: <1%	aircraft, boats, railroad cars, and machinery because of its high strength and resistance to corrosion
Nichrome	nickel: 80–85% chromium: 15–20%	heating elements in toasters, electric heaters, etc.
Phosphor bronze	bronze with a small amount of phosphorus	springs, electrical springs, boat propellers
Solder	lead: 50%, tin: 50% or tin: 98%, silver: 2%	joining two metals to each other  joining copper pipes
Sterling silver	silver: 92.5% copper: 7.5%	jewelry, art objects, flatware
Type metal	lead: 75–95% antimony: 2–18% tin: trace	used to make type for printing because it expands as it cools