


# US 90 in Beaumont District

- Liberty County, US 90 RM 847
- Project Completed ; 2000
- Thickness ; 10-in
- Base type ; Existing 6" Flexible Base
- Subgrade type ; -
- West (Dayton Direction) ; Gravel
- East (Liberty Direction) ; Limestone(?) or ...
- Survey Date ; 03-15-2012







8  
7  
4

03.15.2012 14:04

# Dayton Direction

- CAT ; Gravel
- Overall CPCD Condition ; Not Good
- Observed Distresses
  - Small Map Cracking, Transverse Cracking, Longitudinal Cracking
  - PCP, Diamond Grinding.

# Small Map Cracking

03.15.2012 13:49





03.15.2012 13:50



03.15.2012 13:51



03.15.2012 13:51



03.15.2012 13:52



03.15.2012 13:52





03.15.2012 13:54



# Transverse Cracking



03.15.2012 14:08



# Longitudinal Cracking



03.15.2012 13:48





03.15.2012 13:49





03.15.2012 14:07





03.15.2012 14:08

# Diamond Grinding



03.15.2012 13:48





03.15.2012 13:50





03.15.2012 13:55

PCP





03.15.2012 14:02



03.15.2012 14:06





03.15.2012 14:07



03.15.2012 14:07



# PCP Aggregate ; Limestone



03.15.2012 14:08





03.15.2012 14:09





03.15.2012 14:09



03.15.2012 14:09





03.15.2012 14:09



03.15.2012 14:09



# Liberty Direction

- Construction Year ;
- CAT ; Limestone(?) + ?
- Overall CPCD Condition ; Very Good
- Observed Distresses
  - Exposed Dowel 1ea



03.15.2012 13:56





03.15.2012 13:56



03.15.2012 14:05





03.15.2012 13:56





03.15.2012 13:57





**Dayton Direction ; Gravel**

**→ Liberty Direction ; Limestone**

03.15.2012 13:57

# Exposed Dowel





03.15.2012 13:58





03.15.2012 13:58





03.15.2012 13:58





03.15.2012 13:58