

Geobrugg AG
Geohazard Solutions
Aachstrasse 11 • CH-8590 Romanshorn
Fax +41 71 466 81 50
www.geobrugg.com



CAN Geotechnical

Our reference: Duncan Ecclestone
Direct:
E-mail: Duncan.Ecclestone@geobrugg.com

27.02.2018

Your reference:

East side Catchments RXE-5000 Rock fall fence 2018

Dear Hazel

After the site inspection undertaken on the 21st February 2018 I am happy to confirm that the system built on site is compliant with our product manual and all items have been correctly installed.

During the site inspection I was unable to confirm the torque applied to all wire rope clips but did undertake a visual inspection off all low level clips and could clearly see that the rope has been squeezed at each clip location. Which suggest that torque has been applied. Speaking with Phil Clark he confirmed that all clips had been tensioned.

It is essential that the fence is inspected as a minimum annually to ensure that no small parts have been stolen or misplaced. After periods of heavy rainfall it may be necessary to take a site walk through to ensure that the system has not been impacted by rock fall.

Please use the GBE-RXE Series e Maintenance manual 07 dated 13.07.2017 to inspect the fence and to undertake any maintenance requirements.

If you have any further request or enquiries please do not hesitate to contact Geobrugg direct.

Yours faithfully
Geobrugg AG

A handwritten signature in blue ink, appearing to read 'D. Ecclestone', is positioned above the printed name and title.

Duncan Ecclestone
Country Manager UK / ROI