


Frequency - Response Compensation

We will analyze various compensators using frequency response techniques such as:

- 1- PD, P
- 2- Lead
- 3- PI / Lag
- 4- PID compensators

Consider the system w/o compensation



the closed loop characteristic equation is:

$$1 + KG(s) = 0$$

When a compensator $D(s)$ is added, the closed-loop characteristic equation changes to:

$$1 + KD(s)G(s) = 0$$

$KD(s)G(s)$
new open-loop transfer function

Recall that for a general system:

1. The open-loop stable system is stable in closed-loop if the open-loop magnitude frequency response has

$$|KG(j\omega)| < 1 \quad \text{at} \quad \angle G(j\omega) = -180^\circ$$

"Holds for systems when increasing the gain leads to instability and $|KG(j\omega)|$ crosses the $\text{mag}=1$ once."

2. Percent overshoot for 2nd order system can be reduced by increasing the phase margin

$$\text{PM} \cong 100\xi$$

"Increasing PM, increases ξ "

3. Increase the speed of response by increasing the bandwidth:

Recall:

$$T_s = \frac{4}{\omega_{BW} \xi} \sqrt{(1 - 2\xi^2) + \sqrt{4\xi^4 - 4\xi^2 + 2}}$$

4. Steady-State error is improved by increasing the low-frequency magnitude response

Example: Recall for type 0 system

$$G(j\omega) = K_0 \frac{\prod_{i=1}^n (j\omega\tau_i + 1)}{\prod_{i=1}^m (j\omega\tau_i + 1)}$$

$$e_{ss} = \frac{1}{1+K_p} \quad \text{where} \quad K_p = K_0$$

The 4 basic realizations will serve as a design guideline to designing compensators in the frequency-domain (response).

These guidelines in conjunction with Bode plots and Nyquist diagrams only serve as basic guidelines and the designer can develop his/her techniques based on experience and concepts of frequency-response methods.

I. Proportional Control (Gain adjustment)

Compensator:

$$D(s) = K$$

We can increase/decrease K to obtain desired transient response.


Consider a standard open-loop second order system

$$G(s) = \frac{\omega_n^2}{s(s + 2\zeta\omega_n)}$$

then the closed loop t.f. is:

$$T(s) = \frac{\omega_n^2}{s(s + 2\zeta\omega_n) + K\omega_n^2}$$

The root locus:




As K increases, it effects the dampening ratio ζ . In frequency-response approach we know that phase Margin is related to ζ by:

$$PM = \tan^{-1} \frac{2\zeta}{\sqrt{1+4\zeta^4} - 2\zeta^2} \quad \left. \vphantom{\frac{2\zeta}{\sqrt{1+4\zeta^4} - 2\zeta^2}} \right\} \text{for 2nd order system.}$$

OR

$$PM \cong 100\zeta \quad 0 \leq PM \leq 60^\circ$$

But what is the PM graphically?



But what happens if the PM margin of the uncompensated system is not desirable based on ζ ? Then we can increase/decrease K to change PM.

From plot, we need to increase by amount AB to shift magnitude plot up by AB .

Note that shifting the magnitude plot up/down by varying the gain does not affect the phase!

Procedures

1. Draw bode Magnitude / phase plots for some convenient gain, K .
2. Compute the required phase margin from desired ζ or %OS


$$\zeta = \frac{-\ln(\%OS/100)}{\sqrt{\pi^2 + \ln^2(\%OS/100)}}$$

$$PM = \tan^{-1} \frac{2\zeta}{\sqrt{-2\zeta^2 + \sqrt{1 + 4\zeta^4}}}$$


3. Find the frequency ω_{ϕ_m} on Bode phase diagram that yields the desired PM.
4. Change the gain by amount that corresponds to the appropriate PM so that new magnitude plot goes through 0dB at ω_{ϕ_m} .


Example

Find K to yield 9.48% overshoot.



Recall from the Root locus method:





step 1 obtain ζ and PM

$$\zeta = \frac{-\ln(\%OS/100)}{\sqrt{\pi^2 + \ln^2(\%OS/100)}} = 0.6$$

$$\Rightarrow PM = \tan^{-1} \frac{2\zeta}{\sqrt{1+4\zeta^4} - 2\zeta^2} = \underline{\underline{59.19^\circ}}$$

step 2 Draw bode plot for arbitrary K

choose $K = 3.6$

Matlab commands:

```
>> K = 3.6
```

```
>> n = 100 * K
```

```
>> d1 = [1 100 0]
```

```
>> d2 = [1 36]
```

```
>> d = conv(d1, d2)
```


```
>> sys = tf(n, d)
```

```
>> bode(sys)
```

```
>> [Gm, Pm, Wcg, Wcp] = margin(sys)
```

$G_m = 1360$

$P_m = 89.78$



Step 3

Find $\omega_{\phi_{m_{des}}}$ to get $PM = 59.19^\circ$

$$\phi = -180^\circ + 59.19^\circ = -120.81^\circ$$

$$\Rightarrow \omega_{\phi_{m_{des}}} \approx 14 \text{ rad/s}$$

Step 4

Compute the new K

Bode plot was for

$$K_1 = 3.6$$

Need an increase in 44dB gain

$$K_2 = 10^{(44/20)} = 158.5$$

then new K


$$K = K_1 \times K_2$$

$$K = (3.6)(158.5)$$


$$\boxed{K \approx 570.6} \Rightarrow \text{Verify w/ Matlab!}$$

Bode Diagrams

Gm=8.58 Pm=59.73



Step Response



II PD Compensation

compensator:

$$D(s) = K + K_d s$$


Was shown to have a stabilizing effect on the root locus of a 2nd order system.

Lets look at Bode Plot for $D(s)$ only!

$$D(s) = K_d s + K = \left[\frac{K_d}{K} (j\omega) + 1 \right] K$$

Break Point:

$$\omega_{BP} = \frac{K}{K_d}$$



So, what effects does adding a PD controller have on the closed-loop system?

From the Bode Plots, a PD controller will increase the phase Margin of the system by adding more gain beyond the break point frequency, hence add more damping.

However, since the gain continues to grow as ω increases, this is undesirable when systems have noise.


Lead Compensation

Recall the problem of increase amplification in PD compensator. To alleviate this problem, a pole is added at frequencies higher than the break point of a PD which results in a lead compensator:

$$D(s) = K \frac{T_s + 1}{\alpha T_s + 1} \quad \text{where } \alpha < 1$$


Note that since $\alpha < 1$, then the pole is further in the LHP than the zero.

let's look at Bode Plot:



What effects Does lead have on a system?

- 1- Phase increase (or lead)
- 2- Improves dampening of the system



From the equation:

$$D(s) = K \frac{Ts + 1}{\alpha Ts + 1} = K \left(\frac{1}{\alpha} \right) \left(\frac{s + 1/T}{s + 1/\alpha T} \right)$$

the phase contribution is:

$$\phi = \tan^{-1}(T\omega) - \tan^{-1}(\alpha T\omega)$$

the Maximum phase occurs at:


$$\omega_{\max} = \frac{1}{T\sqrt{\alpha}}$$

where

$$\phi_{\max} = \sin^{-1} \left(\frac{1-\alpha}{1+\alpha} \right)$$

OR

Maximum phase occurs between the 2 break point frequencies or also known as the corner frequency.


$$\alpha = \frac{1 - \sin \phi_{\max}}{1 + \sin \phi_{\max}}$$

Related to standard transfer function form:

$$D(s) = K \frac{(s+z)}{(s+p)} \quad \text{where } z = 1/T$$
$$p = \frac{1}{\alpha T}$$

then we have

$$\omega_{\max} = \sqrt{|z||p|}$$

and

$$\log \omega_{\max} = \frac{1}{2} (\log |z| + \log |p|)$$

Basic Design Guidelines:

1. The amount of phase lead at ω_{\max} only depend on α .
2. The maximum phase lead increase is limited to 90° .
3. Rule of thumb is to use one lead compensator to provide up to 60° of phase lead. More would result in too much amplification at higher frequencies.

Design Procedure for Lead Compensator:

Case 1: Design for low-frequency gain (e_{ss} error specs)

1. Determine K to satisfy e_{ss}

Case 2: Design for closed-loop bandwidth

1. Determine open-loop cross-over frequency to be a factor of 2 below bandwidth.


Continue ...

2. Find PM of uncompensated system with the gain K .
3. Find ϕ_{max} plus small amount (5° to 12°)

$$\phi_{max} = PM_{des} + \text{Extra} - PM_{\text{uncompensated system}}$$


4. Determine α

$$\alpha = \frac{1 - \sin \phi_{max}}{1 + \sin \phi_{max}}$$



then

5. Determine ω_c (cross over frequency)
to be ω_{max} (Trial Error, but you can
start by):



Search for $20\log\sqrt{\alpha}$ on Mag. plot. find
frequency at which this occurs then
use it for ω_{max}

$$\omega_{max} \approx \omega_c$$

6. Solve for the zero and poles:

$$D(s) = K \left(\frac{1}{\alpha} \right) \frac{s + 1/T}{s + 1/\alpha T}$$

$$\frac{1}{T} = \omega_{\max} \sqrt{\alpha}$$

$$\frac{1}{\alpha T} = \frac{\omega_{\max}}{\sqrt{\alpha}}$$

7. Plot Bode diagram for new system and then check PM and ess.

8. Draw closed-loop bode plot to get closed-loop bandwidth.

9. Iterate the design.

Example (lead compensator)

Consider the 3rd order System:

$$K G(s) = \frac{K}{(2s+1)(s+1)(0.5s+1)}$$

Design a lead compensator such that

$$K_p = 9 \text{ and } PM = 25^\circ$$

Solution

step 1: Find K given $K_p = 9$

$$\text{since } D(s) = \frac{1}{\alpha} \left(\frac{s + 1/T}{s + 1/T\alpha} \right) \text{ with}$$

$$D(0) = 1, \text{ then}$$

$$e_{ss} = \frac{1}{1+K_p} \Rightarrow K_p = \lim_{s \rightarrow 0} K D(s) G(s) = K$$

$$\Rightarrow \underline{\underline{K_p = K = 9}}$$


step 2

Draw the bode plot with $K=9$ and find the PM in Matlab.

$$PM \approx 7^\circ$$

$$9/[(2s+1)(s+1)(0.5s+1)]$$

$$[gm=1.25 \quad pm=7.12]$$



Step 3

Allowing extra 5° of PM we find ϕ_{max}

$$\phi_{max} = PM_{des} + 5^\circ - PM_{vc}$$

$$\phi_{max} = 25^\circ + 5^\circ - 7^\circ$$

$$\underline{\phi_{max} = 23^\circ} \quad \text{Want lead to contribute.}$$

Step 4

find α :

$$\alpha = \frac{1 - \sin 23^\circ}{1 + \sin 23^\circ} = 0.43$$

Step 5

Determine the cross over frequency at which the new PM boost should occur.


$$Mag = 20 \log(\sqrt{\alpha}) = -3.66 \text{ dB}$$

Find -3.66 dB on Magnitude plot then find ω_c , then

$$\omega_c \approx \omega_{max} = \underline{\underline{2.1 \text{ rad/s}}}$$

$$9/[(2s+1)(s+1)(0.5s+1)]$$

$$[gm=1.25 \quad pm=7.12]$$



Step 6 Solve for the poles and zeros:

$$KD(s) = K \left(\frac{1}{\alpha} \right) \frac{s + 1/\tau}{s + 1/\tau\alpha}$$

$$\frac{1}{\tau} = \omega_{\max} \sqrt{\alpha} \cong \omega_c \sqrt{\alpha}$$

$$\Rightarrow \frac{1}{\tau} = (2.1) \sqrt{0.43} \cong 1.38$$

$$\frac{1}{\tau\alpha} = \frac{1}{\alpha} (1.38) = 3.2$$

so:

$$D(s) = 9 \left(\frac{1}{0.43} \right) \left(\frac{s + 1.38}{s + 3.2} \right)$$

$$D(s) = 20 \left(\frac{s + 1.38}{s + 3.2} \right)$$


Step 7 Check to see if conditions are met in Matlab.

$$PM = 19.4^\circ$$

Iterate if necessary!

Compensated System

[gm=1.84 pm=19.42]



IV PI Compensation

Used to reduce bandwidth and minimize the steady state error.

$$D(s) = K + K_i \left(\frac{1}{s} \right)$$


There is an infinite gain at zero frequency which reduces steady state error.

look at the Bode Plots:


$$D(s) = \frac{SK + K_i}{s}$$

$$D(s) = \frac{K_i \left(\left(\frac{K}{K_i} \right) s + 1 \right)}{s}$$

Magnitude:



Phase:



By examining the phase & Magnitude plot, we notice:

1. Gain increase below break point frequency
2. Phase decrease below break point frequency.

PI Design Guidelines:

Design PI such that the phase decrease occurs below the systems desired cross-over frequency to reduce the effects of decrease phase margin!

V Lag Compensation


Lag compensation approximates a PI controller.




the transfer function:

$$D(s) = \alpha \frac{Ts + 1}{\alpha Ts + 1} \quad \text{where } \alpha > 1$$

In this form we note that the pole has a lower break-point frequency than the zero. Which results in a low frequency increase in amplitude and phase decrease (lag).

Bode Plot for lag:





By examining the Bode Plot, the primary objective of lag include:

1. Provide additional $+20 \log(\alpha)$ gain at low frequency
2. Leave the system sufficient phase margin.
3. Improves steady state error, but does not greatly affect transient response.

Lag Design Guidelines

1. zero + pole location of lag are selected to be much smaller than the uncompensated system crossover frequency in order to affect PM to a minimum.
2. Reduce steady state error by increasing the low frequency gain, hence placing zero / poles close to $j\omega$ -axis in s -plane.

Lag Design Procedure

Compensator :

$$D(s) = \alpha \frac{Ts + 1}{\alpha Ts + 1} \quad \alpha > 1$$

1. Determine K (open-loop) that meets the phase margin requirements w/o compensation.
2. Draw Bode plot of uncompensated system with gain K , then find low frequency gain.
3. Determine α to meet low frequency gain condition.
4. Choose $\omega = \frac{1}{T}$ (zero of lag) to be one octave or decade below the new crossover frequency (ω_c)
5. The other corner frequency (pole) is then $\omega = 1/\alpha T$
6. Iterate on design.

Example (Lag Compensation)

Consider again the same 3rd order system as for the lead design.

$$G(s) = \frac{K}{(2s+1)(s+1)(0.5s+1)}$$

Design lag such that $PM = 25^\circ$ and $K_p = 9$

solution

step 1

Find K to satisfy $PM = 25^\circ$: Plot Bode plot then determine K to give $PM = 25^\circ$.
we choose $PM = 30^\circ$ w/ fudge factor.


$$K \approx (1) * 10^{(14/20)}$$

$$K \approx 5.0$$

Plot Bode Again to verify $PM \approx 30^\circ$.

then we get $\omega_c \approx 1.3 \text{ rad/s}$

$$G(s) = 1/[(2s+1)(s+1)(0.5s+1)]$$




$$\text{Set } K \approx (1) * (10)^{(20/14)} \approx 5.0$$

this will give us a $PM \approx 30^\circ$

K=5.0

Bode Diagrams

Gm=2.25 Pm=29.15



step 2

low frequency gain is $K = 5.0$

at $\omega_c = 1.3 \text{ rad/s}$

step 3

Determine α

want $K_p = 9$

$$K_p = \lim_{s \rightarrow 0} D(s)G(s) = \lim_{s \rightarrow 0} \alpha \left(\frac{Ts+1}{\alpha Ts+1} \right) \frac{K}{(2s+1)(s+1)(0.5s+1)}$$

$$\Rightarrow \alpha K = 9$$

$$\alpha(5.0) = 9 \Rightarrow \boxed{\alpha = 1.8}$$

step 4

choose $\omega = 1/T$ to be at least 10 times less than $\omega_c = 1.3 \text{ rad/s}$

$$\text{let } \omega = 1/T = 0.2$$

$$\Rightarrow T = 5$$

$$\Rightarrow \alpha T = 9$$

so compensator becomes:

$$D(s) = 1.8 \frac{5s+1}{9s+1}$$

Step 6

check the design

$$D(s)G(s) = 1.8 \frac{5s+1}{9s+1} \cdot \frac{5.0}{(2s+1)(s+1)(0.5s+1)}$$


$$D(s)G(s) = 9 \frac{(5s+1)}{(9s+1)(2s+1)(s+1)(0.5s+1)}$$

when we check with Matlab, we
get

$$\underline{\underline{PM = 24.75^\circ}}$$

Bode Diagrams

with D(s)



VI PID Compensation

— the combination of a lead and lag compensation.

$$D(s) = K + K_d s + K_i \left(\frac{1}{s} \right)$$

Provides simultaneous improvement in transient and steady-state response.

Guidelines:

1. Design the lag portion to meet e_{ss} conditions
2. then Design the lead portion to take care of transients.