

Gold Standard Service Corp.**P.O. BOX 4831****Rancho Cucamonga, CA 91729**

gold-standard@hotmail.com

(877)313-3552 Of...



Invoice

Date: 6/3/2022**Invoice #** 36908**Work Order #** 36908**Bill To**Total Transportation & Distribution
210 East Lambert Road,
Fullerton, CA 92833**Ship To**210 E. Lambert Rd.
Fullerton, CA**P.O. #** LS210-S7-51520**Unit #** S7**Hour Meter:** 2900**Serial #** SA-06-05145**Terms:** Due on receipt**Due Date:** 6/3/2022**Ship Date** 6/3/2022 **Tech:** JR**Model:** RaymondSACSR30T

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: 6/2 Check side gate and code 29. Repair right side gate pivot screw thread. Drill and tap. Install shelf coil. Install new pivot and snap ring. Replace right console gas spring. 6/3 Install rebuilt drive motor shaft with brake. Replace main height manager.	5	121.50	607.50
Drive motor Rebuilt Shaft	1	1,072.50	1,072.50T
Heli Coil 1/2 x 24	1	10.45	10.45T
Pivot Stud	1	62.70	62.70T
Snap Ring	1	6.95	6.95T
Spring	1	91.75	91.75T
Height Manager	1	979.69	979.69T

Thank you for choosing Gold Standard Service for all your material handling needs.

Subtotal	\$2,831.54
Sales Tax (9.5%)	\$211.28
Total	\$3,042.82
Payments/Credits	\$0.00
	\$3,042.82

Remit To: Gold Standard Service Corp.
P. O. Box 4831
Rancho Cucamonga, CA 91729